ECS	Configuration	Change	. Juest
	Somigaration	Onange	. Jucai

e 1 of $\stackrel{\checkmark}{5}$ Page

CCR No.	98-	00	80	L	_ogged l	Date	1/22/	98	Rev	Request Type CCR		
Priority	Ro	utine		Ur	gent 🔲	E	mergency	X	Affected Release	Rel: 2	Change Class II	
Title (description) GSFC Cable Management Plan												
Documents Affected								Source Nos (RID, NCR, Action Item, EDC CCR, etc.) or Tech Reference				
920-TDG-005 Rev:03							NIA					
RTM Chan	ge		S	tart N	New Bas	eline	· 🗌		1			
Problem Requirements for fail over design caused the reconfiguration of the GDAAC cable management plan												
Proposed Solution												
The attached cable management plan now reflects the as built at launch configuration for GDAAC												
Need by CO	B : 1/2	23/98		ı								
Immost An	-lusi				···		<u> </u>					
		ected:		BO Q Securi	ic 🗵		Contracts Rel. Dev subcontrot	ı	ECS Chief Eng Rel. A Sys. Eng	FOS Rel. C Sys Verl _x Acpt	M&O X SCDO Arch.	
Cost:	••••••	••••••	••••••	Noi	ne 🔲		Small Not exceeding \$10	00.000)	Medium	Large (Over \$500,000)		
Schedule: Additio		oc		No	one 🔲		Other	*************	Man-Mont	ns		
Materia	als											
Originator	Tim.	Wells	ext. 40)21			othy E. We	ells	Limothy E.	Well	2 ' /- 22-98 Date	
Office M&	0		_ Of	fice M	Manager		n Jaeger gnature	<u> </u>	lam Wy	heer	//22/98 Date	
Dispositio	n		Appr	roved	×	Α	pproved w/	'Comr	nent For	vard 🔲	Disapproved	
Comments	:)	
			CCB (Chairp	oerson	Teri	ry Fischer		TWF	rike	//23/ 98	

CM0.OC96

ORIGINAL

ECS